Work	Orde	r ID	57601
MINN	. Oluci	I III	3/001

Friday, April 09, 2010 1:33:28 PM



Page 1

Insp.

Stamp

Item ID: D3929-042 Accept Setup Start **Revision ID:** Stop Item Name: Gusset Assembly **Start Date:** Start Qty: 6.00 4/12/2010 **Cust Item ID: Required Date: 4/15/2010**. Req'd Qty: 6.00 **Customer:** Reference: Run Start Process Plan: MF Date: 10-4-9 Approvals: Tooling: Date:_ Stop Date: _____ SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Draw Reject Draw Plan Reject Accept Work Center ID **Description Run Hours** Number Rev. · Code Qty **Qty** Number **Draw Nbr Revision Nbr** D3929 Α 100 0.00 18/4 104-12 Waterjet 0.00 Memo FLOW CNC Waterjet 1-Cut as per Dwg D3929 Dwg Rev: Prog Rev: 2-Deburr if necessary

110

Quality Control

Memo

QC2- Inspect parts off machine FAI/FAIB

0.00

0.00

B10-4-17

Dart Aerospace Ltd

W/O:			V	ORK ORDER CHANG	ES					
DATE	STEP	PRO	OCEDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Ca	tegory:	_ NC	R: Yes	No DQ	A:	Date:	<u> </u>
	R	esolution:	Disposit	ion:	_ QA	N/C CI	osed:		Date:	
NCR:			WORK OR	DER NON-CONFORMA	ANCE	(NCR)			
DATE	STEP	Description of NC		Corrective Action Secti	on B		Verific	ation	Approval	Approval
	O.L.	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date		ion C	Chief Eng	QC Inspector
										-
								;		·
										-
								•		<u> </u>

Work Order ID 57601

Friday, April 09, 2010 1:33:28 PM



Page 2

Item ID:

D3929-042

Accept

Setup Start

Stop

Stop



Revision ID:

Item Name:

Gusset Assembly

Start Date: Required Date: 4/15/2010

4/12/2010

Start Qty: 6.00

Req'd Qty: 6.00



Cust Item ID:

Customer:

Number

Reference:

Approvals:

Process Plan: _____ Date: ____

Date:

Tooling: SPC (Y/N): Date: Date: Run Start

QC:

Sequence ID/

Work Center ID

120

OC

Quality Control

Operation Description

QC8- Inspect parts - second check

Memo

Set Up/ **Run Hours**

0.00

wolon 12 0.00

Draw Draw

Plan Rev. Code

Accept Qty

Reject Qty

Reject Insp. Number Stamp

130

Packaging Packaging

-Pick Kit

0.00

Memo

0.00

0.00

Cpl-10.04.20

140

Large Fab Large Fab

Memo

0.00

Weld bushings D3907-1 as per dwg D3929

316L rod batch: 11679

Dart	Aero	space	Ltd
	~~	JUGG	

W/O:			W	ORK ORDER CHANG	iES				
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			-						
Part No	:	PAR #:	Fault Cat	egory:	_ NCR: Ye	es No D	QA:	_ Date: _	<u> </u>
	R	esolution:	Dispositi	on:	_ QA: N/C	Closed:	· · · · · · · · · · · · · · · · · · ·	Date: _	
NCR:	· ·		WORK ORE	DER NON-CONFORM	ANCE (N	CR)			
DATE	STEP	Description of NC			ion B	Ver	ification	Approval	Approval
	0.2.	Section A	Initial Chief Eng	Initial Action Description Chief Eng Chief Eng			ection C	Chief Eng	QC Inspector

Work Order ID 57601

Friday, April 09, 2010 1:33:28 PM



Page 3

Item ID:

D3929-042

Accept

Setup Start

Stop

Revision ID: Item Name:

Gusset Assembly

Start Date:

4/12/2010

Start Qty: 6.00

Req'd Qty: 6.00



Cust Item ID:

Customer:

Reference:

Approvals:

Required Date: 4/15/2010

Process Plan:

Date:

Date: _____

Tooling: SPC (Y/N): Date:

Date:

Start Run

Stop



Sequence ID/ **Work Center ID**

150

Quality Control

Operation Description

QC9- Inspect visual per QSI004- Fusion Welds

Memo

Memo

Identify as per dwg & Stock Location

Set Up/ **Run Hours**

0.00

0.00

Draw Number

Plan Draw Rev. Code Accept Qty

Reject Qty

Reject

Insp. Number Stamp

160

Quality Control

QC5- Inspect part completeness to step on W/O

0.00

170

Packaging Packaging

Memo

0.00

0.00

Dart Aerospace Ltd

W/O:			WORK ORDER CHANGES								
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
				v							
							1				
Part No	•	PAR #:	Fault Categ	jory:	_ NCR: Yes	No DQ	A:	Date:	B. 7 1 22 2		
		olution:									
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCF	?)					
DATE	STEP	Description of NC		Corrective Action Section		Verific	cation	Approval	Approval		
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		ion C	Chief Eng	QC Inspector		
									-		
·											
				•							

Work Order ID 57601

Friday, April 09, 2010 1:33:28 PM



Page 4

Item ID:

D3929-042

Accept

Setup Start



Revision ID:

Start Date:

Item Name: Gusset Assembly

4/12/2010

Start Qty: 6.00

Required Date: 4/15/2010

Req'd Qty: 6.00



Cust Item ID:

Customer:

Reference:

Approvals:

QC:

Process Plan:

Date: _____

Tooling: Date:

SPC (Y/N):

Set Up/

Date:

Date:

Start

Stop



Stop

Sequence ID/

Work Center ID

180

QC

Operation **Description**

QC21- Final Inspection - Work Order Release

Memo

Run Hours

0.00

Draw Number Rev.

Draw Plan Code

Accept Qty

Reject Qty

Run

Reject Number Insp. Stamp

Quality Control

0.00

Dart Aerospac	e Ltd
---------------	-------

		- -							
W/O: WORK ORDER CHANGES									
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			V/40 1.0						
Part No	:	PAR #:	Fault Categ	ory:	NCR: Yes	No DQ	A:	_ Date: _	
	R	esolution:	Disposition	:	QA: N/C CI	osed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORMAN	ICE (NCR)			
DATE	STEP	Description of NC		Corrective Action Section	B Sign &	Verific	cation	Approval	Approval
		Section A	Chief Eng	Initial Action Description Chief Eng Chief Eng			on C	Chief Eng	QC Inspector
									-
								· · · · · · · · · · · · · · · · · · ·	
	1					1			

Picklist Print

Friday, April 09, 2010 1:33:28 PM

Work Order ID: 57601

D3929-042

Parent Item Name: Gusset Assembly

Comments:

Parent Item:



57242

Start Date: 4/12/2010

Required Date: 4/15/2010

Start Qty: 6.00

Required Oty: 6.00

Page 1

Component Item ID/	Replacement	Mfg/	Bin	Primary	Last	Route	Unit of	Qty on	Remaining	Qty	Date	Status
Item Name	Item ID	Purch	Item	Location	Location	Seq ID	Measure	Hand	Qty To Pick	Issued	Issued	
M304S11GA		Purchased	No			100	sf	33.8200	2.8421	s. 4	B10-4-13	

Warehouse Location	Loc Oty	Loc Code
Main Warehouse		
MAT19	33.82	
112663	33.82	

117663

D3907-1 Bushing

Manufactured

Each 59.0000 12.0000

Warehouse Loc Qty Loc Code Location Main Warehouse WA 59 56517 18

41

130

W/O:			V	ORK ORDER CHAN	GES			 	
DATE	STEP	PRO	OCEDURE CH	IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Ca	tegory:	NCR: Yes	No DQ	A:	Date:	
		solution:							
NCR:	I	,	WORK OR	DER NON-CONFORM	ANCE (NC	₹)			
DATE	STEP	Description of NC			ection B	Verific	cation	Approval	Approval
	OIL!	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sect	ion C	Chief Eng	QC Inspector
									-
•									
						,			
	1						•		ľ

DART AEROSPACE LTD	Work Order:	57601
Description: Support Gusset	Part Number:	D3929-1
Inspection Dwg: D3929 Rev: A		Page 1 of 1


FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Com	ments
Ø0.375	+0.006/-0.001	,311	7			· · · · · · · · · · · · · · · · · · ·	
0.500	+/-0.010	602,	Ŭ				
0.500	+/-0.010	· 500	~				
4.036	+/-0.010	4.038	15				
4.382	+/-0.010	4.038	Y				
8.274	+/-0.010	8.775	4			112.4	
10.915	+/-0.010	10,910	`8				
1.000	+/-0.010	1.004	Ÿ				
11.198	+/-0.010		200		,		
0.500	+/-0.010	.900	2	-			. "
1.572	+/-0.010	1,575	Y				
0.125	+/-0.010	117	8			-	•
				_			
					,		
·							
						······································	
							
						<u> </u>	
	1	L.—			<u> </u>		


Measured by: R	Audited by:	Prototype Approval:	N/A
Date: 10-4-12	Date: 10lou 12	Date:	N/A

Rev	Date	Change		Revised by	Approved
Α	09.05.27	New Issue	P/O D3929-041/-042	KJ of	




Dart Aerospa	ce	Ltd
--------------	----	-----

W/O:			WC	RK ORDER CHANG	SES	·		
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву	Date C	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	jory:	_ NCR: Yes	No DQA: _	Date: _	
Resolution: Disposition:								
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NCR)		· · · · · · · · · · · · · · · · · · ·
DATE	STEP	Description of NC		ion B	Verificati	on Approval	Approval	
DAIL	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C		QC Inspector
	:							
								
	,							



Dart Aerospace Ltd	Oart Aerospac	:e	Lto	d
--------------------	---------------	-----------	-----	---

	•									
W/O:			WC	RK ORDER CHANGE	S		71			
DATE	STEP	PRO	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
						· · · · · · · · · · · · · · · · · · ·				
Part No: PAR #		PAR #:	Fault Cateo	jory:	NCR: Yes	No DQA	\ :	_ Date: _		
Resolution:			Disposition: QA: N/C Close				sed: Date:			
NCR:			WORK ORDE	R NON-CONFORMAN	ICE (NCF	R)				
DATE	STEP	Description of NC	Corrective Action Section B			Verific	ation	n Approval	Approval	
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section	on C	Chief Eng	QC Inspector	
									-	
								·		
									i contract of the contract of	



Dart Aerospace Ltd

W/O:			W	ORK ORDER CHANG	ES			——————————————————————————————————————	
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	·								
			· · · · · · · · · · · · · · · · · · ·						-
			31 W						
Part No:		PAR #:	Fault Cat	egory:	_ NCR: Yes	No DQ	/ :	_ Date: _	
						QA: N/C Closed: Date:			
NCR:		\	WORK ORE	DER NON-CONFORMA	ANCE (NCR)			
DATE	STEP	Description of NC					cation Approval		Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section	on C	Chief Eng	QC Inspector
		. *						·	-
								:	
							÷		